


Port-Industrial Pavement on Existing Asphalt or Concrete



NOTES:

1. EXISTING ASPHALT OR CONCRETE PAVEMENT SHALL BE THOROUGHLY INSPECTED FOR AREAS IN NEED OF PATCHING OR REPLACEMENT. CONDUCT ALL REPAIRS AND FILL ALL CRACKS GREATER THAN 1/4 IN. (7 MM) WIDE PRIOR TO PLACING GEOTEXTILE, SAND, AND PAVERS.
2. PROVIDE DRAINAGE OF SAND LAYER THROUGH PEA GRAVEL-FILLED WEEP HOLE(S) INTO CATCH BASIN(S).



Creating elegant hardscaping environments.

118 International Drive, Suite 101
Morrisville, NC 27560

800-292-7220

www.fredadampaving.com